Approved For Release 2002/10/25 : CIA-RDP80R01731R000200020082-2 11-269/25X1 CONFIDENTIAL 4 APR 1959 Mr. Forest L. Renderson Executive Vice President American Cable & Radio Corporation 67 Broad Street New York 4, New York Deer Mr. Henderson: In the absence of Mr. Dalles, I want to thank you very much for your letter of 30 March concerning the repair operations engaged in by your company on the Main 2 cable. I have read it with a great deal of interest and an sending it on to some of our people here who have been following this situation with considerable interest. We greatly appreciate your courtesy in bringing this information to our attention. With kindest regards. Sincerely, C. P. Cebell General, USAF Acting Director O/DCI/ B April 59 Distribution NOTE FOR RECORD Orig - Addressee Basic, w/cy reply, fwd to Mr. Sheldon 1 - ADCI-Whave "for info and use in USIB Committee" 1 - DD/I (Attn: AD/O w/besic) per General Cabell's instruction. 1 - MAD DUCY . 25X1 ck - ER-W/ay have ORIGINAL CL BY DECL X REVW ON -DOCUMENT NO. Z EXT BYND 6 YRS BX NO CHANGE IN CLASS. [] REASON_ ☐ DECLASSIFIED CLASS. CHANGED TO: TS S C NEXT REVIEW DATE: AUTH: NR 70-2 Approved For Release 2002/10/25 : CIA-RDP80R01731R000200020082-2

25X1

DATE: 1

25X1



American Cable & Radio Corporution

AMERICAN CABLE & RADIO SYSTEM

> 67 BROAD STHEET NEW YORK 4 N F

March 30, 1959

Mr. Allan Dulles, Director Central Intelligence Agency 2430 E Street, N.W. Washington 25, D.C.

Dear Sir:

During the period beginning with the last week in February and continuing until the middle of March 1959, our cable ship "John W. Mackay" was engaged in repair operations on our Main 2 cable which runs between St. John, Newfoundland, and Waterville, Ireland. She sighted four large Russian trawlers in the vicinity at 1600 on March 24th. The location was latitude 470 57° 13° north and longitude 450 46° 9° west. Our cable was badly ridden for a distance of two miles by trawler equipment. The depth of the water at this location is 140/270 fathoms and the area is north of and adjacent to the Flemish Cap.

One of our employees who has served many years on the cable ship reports that Russian trawlers operate exclusively in this area and that trawlers of other nations are encountered closer to shore in shallow water areas.

Our caile ship was unable to omplete repairs because of bad weather and will return to this area approximately April 12th for that purpose. Our cable ship left two mark buoys in the area to indicate the area of operation when she returns to complete the repairs.

Very truly yours,

Forest L. Henderson

Executive Vice President